
Question 38: What are your guidelines for cleanliness of reactor vessel and overhead lines during Turnaround? Do you have limits on reactor temperatures during dry-out to prevent the ignition of coke in the reactor? What actions do you take if coke starts to burn?

Print as PDF:

Tags

[Catalysts](#)

[Emissions](#)

[Fouling](#)

[Mechanical](#)

[Mechanical Integrity \(MI\)](#)

[Operations](#)

[Process](#)

[Reactor Vessel](#)

[Regenerator](#)

[Safety](#)

Year

2019